

VENUS T5C (DS-2350C) VENUS T5C mini (DS-2250C)

USB 3.0 Firmware Update

(Fix compatibility issues in Windows 7 / Windows 8
and Mac 10.7 (Lion) / 10.8 (ML))



Rev 1.1
July 23, 2013


www.AMSElectronics.com

ATTENTION!

- Before using **FwUpdateTool** utility, T5C **must be connected with a USB 2.0 cable.** You will need a HDD in the unit in order to flash the firmware. SSD HDD will not flash when using this utility. There are no Mac utility.
- Please close any open programs and temporarily disable your antivirus software.


AMS is not held responsible for any damage caused by misuse of this utility! Use at your own risk and be aware that your warranty might be void! Do not distribute or post these files on the internet!

1. Click on FwUpdateTool_v1_19_13.exe (Run as administrator)



Old USB 3.0 firmware
255.00.01.42.16

2. Click Load File "JMS539 64PIN PM255.00.03.42.22.BIN"
3. Run



New USB 3.0 firmware
255.00.03.42.22

Programming Success!!

4. Please Turn-OFF the Power and Turn-On Again! Unplug from USB 2.0 and reconnect with the USB 3.0 cable. All Done!!!